



SimSmith file savelmages captures view help running notes



R = 50 X = 0 SWR = 1.005
←W = 0.995 ←W = 1
±V,i=7.052,0.141 ±V,i=7.052,775.7u

50 ohms	318.3p F	10 MHz
0 johms	795.8n H	50 Zo
<none> file	10 MHz	useZo V_
	200 Ql	Plots Plt
	2K Qc	-0.3 xCenter
	0 @MHz	10.19 xScale
locked freq		0 yCenter
		10 yScale


type	numPnts	from	to	name	sweep
lin	100	1	30	G.MHz	y



G.Plit
Plt

//Plots
SetCanvasProperties(xy1,"xLabel",xCenter,xScale,"yLabel",yCenter,yScale);
Plot(LC1.Z,xy1);

clear error clear output commit L S C + -



lin
BANDS

Plt: LC1.Z
Pwr: LC1
Mark SWR: LC1